




Torque Pattern Diagram




4-bolt




8-bolt




12-bolt



16-bolt



20-bolt



24-bolt